



999022568

CABINET T40/2A
SLOW SPIN SPEED
400-500-600 r.p.m.
03-03-2000




999016323

FRONT. " A " - T40/2
27/11/98



999022572

LBCA T40/2A - AF -
05/07/99



03/03/2000

999022570 03/03/2000

ENAMELLED TUB T40G-2A
WITH DOOR GASKET

D001
D002
D003
D031
D015
D390
D820
D024
D018
D019
D750
D280
D800
D840
D410
D830
D320
D220
D290
D500
D270
D140
D820
D380
D250
D300
D200
D015
D440
D072
D057
D420
D330
D350
D340
D130
D069
D071
D480
D470
D032
D620
D490
D810
D021
D016
D210
D008
D360
D640
D590
D530
D310