



VUE A



WIRING HARNESS PARTS

- 5 → [Connector]
- 7 → [Connector]
- 8 → [Connector]
- 9 → [Connector]
- 10 → [Connector]
- 15 → [Connector]



VUE D

